


## RIVER MILE 10.9 REMOVAL ACTION CAPPING OPERATIONS WEEKLY STATUS REPORT

## Summary of capping operations through week ending April 6, 2014


High river flows from the storms that occurred March 29-30, allowed the placement of only one panel of fabric and armoring stone during the week. As of April 6, an estimated 41% of the dredged and capped area has been protected with this armoring layer. Current projections have all work being completed in early to mid-May, 2014. The attached figure shows the section of RM 10.9 where the fabric and stone has been placed to date.


All capping operations were conducted within acceptable water quality monitoring limits.

## Capping Progress to Date Shown in Blue



## Real-Time Water Quality Monitoring





Water Quality Monitoring Locations